

<i>SB Number:</i>	SB 2MH-001	<i>Creation Date:</i> 06/12/2011
<i>Subject:</i>	<i>Engine firmware upgrade information</i>	
<i>Model:</i>	FS-1030MFP/1130MFP/1035MFP/1135MFP	

Contents

Please restart the machine by completely disconnecting and reconnecting the Power cord after upgrading the Engine firmware.

1. Engine Firmware

The **LCD display** remains powered and the power is **not turned OFF**, when pressing the power switch after Upgrading the **Engine firmware**. Therefore, it is necessary to **disconnect** and **reconnect** the **power cord** in order to turn the power **OFF** and **ON**. After reconnecting the **power cord**, the machine starts up and the **LCD** is powered. After this, the machine should reach the **[Ready] state**.

2. Other Firmware

The procedure has not been changed.

Please turn the power OFF and ON after upgrading the Firmware.