Canon

Service Bulletin

COPIER

Issued by Canon Europa N.V.

Model: Ref	î No.:
	570-002
iR2870 iR3570 (F1-	-T01-0M4-10001-01)
iR4570 Date	te:
29-1	10-04

Subject:

Changing descriptions in Service Manual

<Machine specs: Resolution>

Leaf ID: 00072862

Reason:

The descriptions about copy resolution and print resolution are changed.

Changes are shown below in blue.

Previous leaf:

Copy resolution 600 x 600dpi Print resolution 600 x 600dpi

New leaf:

Copy resolution 1200dpi (equivalent) x 600dpi Print resolution 2400dpi (equivalent) x 600dpi

<Service mode: Fixing cleaning settings>

Leaf ID: 00079547

Reason:

The descriptions in the following service mode item are changed.

COPIER > OPTION > BODY > FIX-CLN

Changes are shown below in blue.

Previous leaf:

	COPIER > OPTION > BODY	
Sub-item	Description	Level
FIX-CLN	The machine performs cleaning by feeding blank paper before pick up of wide paper when receiving a pickup command of wide paper after continuous feeding of narrow paper.	
	<setting range=""> 0: No cleaning, 1: Once every 500 sheets at 225deg C regulated temperature and 60-second idling(Default), 2: Once every 200 sheets at 225deg C regulated temperature and 60-second idling, 3: Once every 100 sheets at 225deg C regulated temperature and 60-second idling</setting>	2

New leaf:

	COPIER > OPTION > BODY	
Sub-item	Description	Level
FIX-CLN	Setting the timing at which the fixing pressure roller is cleaned	
	<setting range=""></setting>	
	0: No cleaning(Default), 1: Once every 500 sheets at 225deg C regulated	2
	temperature and 60-second idling, 2: Once every 200 sheets at 225deg C	_
	regulated temperature and 60-second idling, 3: Once every 100 sheets at	
	225deg C regulated temperature and 60-second idling	

<Durables: Pressure roller bushing>

Leaf ID:

00074600

Reason:

The descriptions about Pressure roller bushing's life are changed.

Changes are shown below in blue.

Previous leaf:

As of Sept. 2004

Ref.	Parts name	Parts No.	Q'ty	Life	Remarks
[13]	Pressure roller	RS5-1446-000	2	100,000	iR2270/2870
	bushing			prints	

New leaf:

As of Sept. 2004

Ref.	Parts name	Parts No.	Q'ty	Life	Remarks
[13]	Pressure roller	RS5-1446-000	2	300,000	iR2270/2870
	bushing			prints	