


KYOCERA *Service Bulletin*

SB Number:	SB 2MK-001	Creation Date: 11/11/2011
Subject:	Parts motor fan 40 SP has been discontinued	
Model:	FS-1030MFP/1030MFP/DP/ 1130MFP/1035MFP/DP /1135MFP	

Contents

The **Parts motor fan 40 SP** is not necessary, to ensure proper temperature inside the machine. Therefore this part has been discontinued.



Parts

No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability	
				Old	New	Old	New
1	302H994280 2H994280	-----	PARTS MOTOR FAN 40 SP	1	-	○	-

Serial numbers of affected machines

Type	Serial number
FS-1030MFP/1030MFP/DP/ 1130MFP/1035MFP/DP /1135MFP	October 2011 production

The above mentioned changes have been applied to machines produced after the above mentioned production date.